

TECHNICAL TIPS:

MANF: RCF spa



MODEL: HF Diaphragm:
N350 - N450, ART200A - 300/300A, PFR151,PA121 - 151 -281



When a replacement diaphragm is fitted to the above HF drivers or speaker systems, it is **IMPORTANT** that the correct polarity is observed.

The driver rear cover is marked +



The diaphragm is marked with a +