


PRODUCT SPARE PARTS INFO:

MANF: RCF spa



Unit 17 Lynderswood Farm
 London Road, Black Notley
 Braintree, Essex CM77 8QN
 Tel: 01245 361578
 Fax: 01245 361357
 email: sales@audio-workshop.co.uk

MODEL: MONITOR 8 - MR8


DESCRIPTION: Compact Two way Loudspeaker

LF 8 inch - HF1 inch CD Tweeter

300 watt IEC - 8 ohm


Terminals & Speakon in

PART NO: DESCRIPTION



15410007 HF DIAPHRAGM


11120007 COMPLETE WOOFER
 or
 11420002 RE-CONE KIT
 Glue not included



33092460 CABINET FRONT (BLACK)
 33092890 CABINET FRONT (WHITE)

33092470 CABINET REAR (BLACK)
 33092900 CABINET REAR (WHITE)

33191010 PROTECTION GRILL (BLACK)
 33191080 PROTECTION GRILL (WHITE)



23031390 CROSSOVER ASSEMBLY

83661007 PROTECTION LAMP

To fit replacement speaker chassis pull off front grill. Remove 4 screws holding speaker, fit new chassis.
 To replace the HF diaphragm remove bass speaker and all screws holding cabinet front to rear. Split cabinet.
 Remove 4 screws on metal HF cover plate then 2 screw from clamp plate. Note the cable colours (see terminal
 with + mark) Carefully extract magnet and diaphragm assembly. Re-assemble and test.



**Please refer all repairs to a Qualified audio / electronics engineer.
 240v ac mains is lethal if not teated with respect.**